

# Improving the Performance of Your 5-Axis Milling Machine

Craig Chester

Product Manager PowerMill and Fusion360




# 5 Axis Machining: Why?




- Fewer setups
- Shorter, more rigid tools
- Reduced cycle time

# “5 Axis” What does that mean?




# “5 Axis” What does that mean?






# “5 Axis” What does that mean?



# “5 Axis” What does that mean?





# “5 Axis” What does that mean?

Matsuura Maxia: MAM72-100H Horizontal 5 Axis



## Axis Structure

### Rapid/Cutting Feedrate


X/Y-axis 60,000 mm/min  
(2,362.20 ipm)

Z-axis 50,000 mm/min  
(1,968.50 ipm)

### Rapid/Cutting Feedrate (A/B)

A-axis 50 min<sup>-1</sup>

B-axis 75 min<sup>-1</sup>



So, is 5 axis machining for me?





# Common beliefs...

- Aerospace



# Common beliefs...

- Injection Molds



# Common beliefs...

- Military and Defense






Common beliefs...

- Think again!

# Common beliefs...

- 5 axis machining is also for everyday simple parts.



With this type of machine, should I  
always work with 5 simultaneous  
axis?






# Of course not!

- 5-axis machines are mostly used for 3 and 3+2 axis machining
  - Simple to program
  - Predictable motion
  - Predictable surface finish
- 3+2 axis machining is often faster than simultaneous machining
  - No large rotary moves over short distances
- Some “5-axis” machines do not support simultaneous machining

# 3+2 axis Vs 3 axis

- 3+2 axis machining can reduce the number of Setups required for part manufacture



# 3+2 axis Vs 3 axis


- Increase the precision of machining by reducing the number of setups







# 3+2 axis Vs 3 axis

- Minimize tool changes




# 3+2 axis Vs 3 axis

- Use of shorter tools




# 3+2 axis Vs 3 axis

- Avoid the purchase of form tools





# 3+2 axis Machining



# The Advantages of Simultaneous 5 Axis Machining?




# A quick explanation of simultaneous 5 axis

- Up to 5 Simultaneous axes:
  - Rotations will be applied throughout the machining
  - The lines of machining code will contain the axes of rotation in addition to the linear axes
  - More advanced programming
  - More complex machine tool motion




# Simultaneous 5 axis



# Simultaneous 5 axis Vs 3+2 axis

- Check the contact point on the tool



# Simultaneous 5 axis Vs 3+2 axis


- Check the contact point on the tool

Operation	Non-tilted cutter	Tilted cutter (10°)
<p>• Semi-finishing <math>a_p = 2 \text{ mm}</math></p> <p>The speed can be further increased by approx. 75% due to the shallow cut and short engagement time:</p> <p><math>v_c = 300 \text{ m/min}</math></p> <p>Feed per tooth, <math>f_z</math>, is the same for both the non-tilted and the tilted cutter, but the effective No of edges, <math>z_c</math>, differs near the centre as described on the previous page.</p>	<p><math>D_c = 10 \text{ mm}</math> <math>D_{cap} = 8 \text{ mm}</math></p> <p><math>v_c = 300 \text{ m/min}</math> <math>n = 11\,940 \text{ rpm}</math></p> <p><math>h_{ex} = 0.08 \text{ mm}</math> <math>f_z = 0.12 \text{ mm/tooth}</math> <math>z_c = 2</math> <math>f_n = 0.24 \text{ mm/r}</math></p> <p><math>v_f = 2\,860 \text{ mm/min}</math></p>	<p><math>D_c = 10 \text{ mm}</math> <math>D_{cap} = 8.9 \text{ mm}</math></p> <p><math>v_c = 300 \text{ m/min}</math> <math>n = 10\,700 \text{ rpm}</math></p> <p><math>h_{ex} = 0.08 \text{ mm}</math> <math>f_z = 0.12 \text{ mm/tooth}</math> <math>z_c = 4</math> <math>f_n = 0.48 \text{ mm/r}</math></p> <p><math>v_f = 5\,100 \text{ mm/min}</math></p>
<p>• Super-finishing <math>a_e = 0.1 \text{ mm}</math></p> <p>The cutting speed can be increased by the factor 3-5 due to the extremely short contact time:</p> <p><math>v_c = 5 \times 170 = 850 \text{ m/min}</math></p> <p><b>Note:</b> In super-finishing a two teeth cutter <math>z_n = 2</math>, should be used to minimize the run-out. With this extremely small <math>a_p</math>, the <math>f_z</math> will be limited by the surface finish demands. Therefore, <math>h_{ex}</math> must be disregarded. A good rule of thumb in super-finishing is to use approx. the same <math>f_z</math> as the <math>a_e</math>.</p> <p><math>f_z = 0.12 \text{ mm/r}</math></p>	<p>A non-tilted cutter is not recommended for super-finishing</p>	<p><math>D_c = 10 \text{ mm}</math> <math>D_{cap} = 4.4 \text{ mm}</math></p> <p><math>v_c = 850 \text{ m/min}</math> <math>n = 61\,100 \text{ rpm}</math></p> <p><math>h_{ex} = 0.02 \text{ mm}</math> <math>f_z = 0.12 \text{ mm/tooth}</math> <math>z_c = 2</math> <math>f_n = 0.24 \text{ mm/r}</math></p> <p><math>v_f = 14\,600 \text{ mm/min}</math></p>




# Simultaneous 5 axis Vs 3+2 axis

- Check the contact point on the tool




# Simultaneous 5 axis Vs 3+2 axis

- Check the contact point on the tool



# Simultaneous 5 axis Vs 3+2 axis


- Check the contact point on the tool
- This tapered tool enables the lower fillet to be machined whilst increasing the rigidity of the tool






# Simultaneous 5 axis Vs 3+2 axis

- Check the contact point on the tool
- This tip radiused, flat bottomed tool machines very efficiently when maintaining a controlled lead angle




# Simultaneous 5 axis Vs 3+2 axis

- Reduced stickout length




# Simultaneous 5 axis Vs 3+2 axis

- Reduced tool stickout





# Problems Caused by Excessive Stickout?



3 Axis Machining

- Greater tool deflection?
  - Poor tolerances
  - Increased probability of chatter
    - Poor surface finish
    - Reduced tool life


CNCCOOKBOOK.COM

Rigidity increases as the 3rd power of stickout.

Reducing stickout from 1.25" to 0.75" buys us 4.63x more rigidity...


<https://www.cnccookbook.com/afraid-tool-deflection/>

# 3 Different ways to use your 5 axis machine tool




3+2 axis Machining

- Cutting has no simultaneous rotary axis cutting motion. Predictable results
- Increased programming time on complex, feature rich parts
- More manual polishing to blend between individual toolpaths



4 Axis Machining  
(Locking one rotary axis)

- Locking the C axis can improve the surface finish as there are no axis reversals or rapid C axis accelerations
- Not suitable for more complex, feature rich geometry




5 Axis Machining

- A single toolpath can cut the whole part. No 'patchwork' required
- Shortest possible tool stickout
- 2 simultaneous rotary axis can degrade the surface finish during sudden axis reversals or changes in acceleration

# Simultaneous 5 axis Vs 3+2 axis


- Machine regions that are difficult to access. For example, undercuts.






# Common 5 axis problems

- Problem? Toolpath exceeds the Y axis range



# Common 5 axis problems

- Solution? Fix the Y axis and replace it with the C axis (Polar Milling)



# Common 5 axis problems

- Problem? Jerky Tool Motion




HuronKX8-Five  
Siemens 840D  
Feedrate:  
7500mm/min




# Common 5 axis problems

- Common Solution? Evenly space the points on the toolpath. This enables the CNC control to process the toolpath faster and more smoothly



Standard Tolerance @Feedrate 7500 mm/min + CYCLE832. Machining time: 82 minutes



MAINTENANCE WARNING				G function	
MKS.DIR\CKC.WPD					
VERY_LATEST_finishing					
[mm]	d-to-go	T,F,S		Auxiliar function	
0.209		T	10.000	D1	
0.000		F	333.0		
			7500. mm/min		
0.094		S	8000. I		
0.239					
5.754					
				Basic block	

Redistributed Points @Feedrate 7500 mm/min + CYCLE832. Machining time: 50 minutes






**39% cycle time saved by  
utilizing evenly spaced  
point distribution**

# Common 5 axis problems

- Problem: Rapid rotary axis acceleration. Typically occurs when the tool axis is close, but not through the machines singularity  
(The machines singularity commonly = the Z axis)

## Simulation analysis



Parameter to display

▼

Display 0 degree line ☐

Display axis limits ☐

☒ Lines    ☒ Time based

☐ Points    ☐ Point based


Tool axis pointing towards spherical center, passing directly over the center point at X0

Tool axis pointing towards spherical center, offset in X by 0.01mm




# Common 5 axis problems

- Problem: Rapid rotary axis acceleration. Typically occurs when the tool axis is close to the machines singularity (The machines singularity commonly = the Z axis)




Is the machine motion smooth?



No! There are 2 rapid C axis accelerations.


# Common 5 axis problems

- Solution 1: Move the tool axis away from the singularity by mounting the part on an angled fixture



The problem: Large C axis move.


This is caused by the toolaxis moving from a +ve to a -ve draft angle, close to the singularity



The same toolpath on the same machine tool now runs smoothly. The fixture has moved the tool axis away from the singularity (Z Axis).

# Common 5 axis problems

- Solution 2: Add more points in the region where excessive rotary action occurs



We can reduce the impact of the problem by adding additional points into the toolpath when simultaneous 5 axis machining close to the machine tools singularity.

This solution is not as effective as fixturing the part away from the singularity, but it is an easier and cheaper method of reducing the negative effects of this problem.



# Results


- Huron KX200 Head-Head configuration

Sample

Point Separation Angle Off



Point Separation Angle 0.

Point Separation Angle  $0.25^\circ$



# Types of 5 axis Machine


- Table/Table





# Types of 5 axis Machine


- Head/Table






# Types of 5 axis Machine

- Head/Head




# Types of 5 axis Machine

- TurnMill



# Types of 5 axis Machine

- Robots







**AUTODESK®**

Make anything™