

MP21049 – How to Achieve Brilliant Surface Finishes for CNC Machining

Jeff Jaje and Wayne Griffenberg
Manufacturing Product Marketing Manager
Instagram & Twitter: JeffJaje



Class summary

Exploring the factors that affect surface finish. This is actually a very large topic, and the majority of time will be spent on the parameters in your CAM system and how they affect surface finish.

Key learning objectives


At the end of this class, you will be able to:

- Understand how tolerance affects surface finish
- Understand how stepover/cusp affects surface finish
- Understand how programming strategy affects surface finish
- See other aspects of the whole CNC milling workflow that affect surface finish

We will have time at the end of class for questions.

Surface Finish

Roughness, Waviness, and Measurement (μm or micron):



Surface Finish



- Roughness – finely spaced surface irregularities. In engineering, what is usually meant by surface finish.
- Waviness – measure of surface irregularities larger than roughness; usually from deflection, warping, vibrations.
- Measurement: actual amount
 - Contact – Stylus
 - Non Contact – interferometry, microscopy, structured light, etc.

Street Definition

- How much time will they have to spend polishing the parts?

Part


Wanted to test on something small, with curvature, steep areas, and radii.



Tolerance


Tolerance – Chordal Deviation

The distance from the point to point movements to the original CAD curve or surface:



Tolerance – tighter tolerance = more points


The tolerance you use when programming is the first important parameter to quality finish:




Tolerance

The tolerance you use when programming is the first important parameter to quality finish:

#4 0.12 mm tolerance




#5 0.001 mm tolerance




Also #3 0.01mm tolerance

Fusion 360



PowerMill



FeatureCAM

Surface Milling Properties - parallel finish

parallel finish

- Settings
 - Dimensions
 - Location
 - Process
 - Misc
- Operations
 - parallel
 - finish1

Tools F/S Coolant Post Variables Milling Leads

Attributes finish1

Check allowance =
Check axial allowance =
* Holder Collision Clipping = False
Index X coordinate =
Index Y coordinate =
Index Z coordinate =
Leave allowance = 0.000
Leave axial allowance =
Machine Maximum Stock = False
Min rapid distance % = 400.000
Orientation angle =
Plunge feed override % = 50.000
Priority =
Stepover = 1.250
Stepover rapid distance =
Target horsepower =
Tolerance = 0.025
Toolpath end =
Toolpath start =
Z end =
Z start =

5-axis position:
Standard

Direction...
Retract/Plunge...
Output Options...


Reset All

New Value:


Set Unset

OK Cancel Apply Preview Help

HSMWorks



Inventor HSM



Tolerance: Mill

Not only do you have the tolerance of the CAM software but you also have the tolerance of the mill and controller.




Tolerance: Mill

Do CNC mills go exactly through every point?

No most have their own tolerances too!

Point Density – How many points (tolerance)

Point Distribution – Even is better



Tolerance: Mill (smoothness while running too)

Some machines:

- Fanuc: P10000 (and others)
- Makino: M250, M251, M252
- Heidenhain: CYCLE DEF 32.0 Tolerance
- Haas: G187 Px E.xx




Tolerance: Mill

If your machine tolerance is low, say .001” – is there any benefit to programming the CAM tolerance tighter?

It depends:

- More points may still help out the controllers splining algorithm
- Too many points may overload the controller.
- Super dense points may introduce “noise” variations making for a slow cut.



PowerMill Parameters – Point Distribution



Stepover/Stepdown – cusp/scallop

Cusp Height


Peak Height from stepover distance



$$\text{Step} = 2 * \text{SQRT} [R^2 - (R - \text{cusp})^2]$$

Cusp Height

Peak Height from stepover distance



Scallop and Stepover

The traditional surface finish provided mainly by your stepover
“Roughness”

#1 0.8 step 0.025 scallop




#2 0.25 step 0.0025 scallop




Also #3 (.16mm step)

Fusion 360



PowerMill



FeatureCAM

Surface Milling Properties - parallel finish

parallel finish

- Settings
 - Dimensions
 - Location
 - Process
 - Misc
- Operations
 - parallel
 - finish1

Tools F/S Coolant Post Variables Milling Leads

Attributes finish1

Check allowance =
Check axial allowance =
* Holder Collision Clipping = False
Index X coordinate =
Index Y coordinate =
Index Z coordinate =
Leave allowance = 0.000
Leave axial allowance =
Machine Maximum Stock = False
Min rapid distance % = 400.000
Orientation angle =
Plunge feed override % = 50.000
Priority =
Stepover = 1.250
Stepover rapid distance =
Target horsepower =
Tolerance = 0.025
Toolpath end =
Toolpath start =
Z end =
Z start =

5-axis position:
Standard

Direction...
Retract/Plunge...
Output Options...


Reset All

New Value:


Set Unset

OK Cancel Apply Preview Help

HSMWorks



Inventor HSM





CAM Strategies

Strategy

What strategies you use to program the part are as important as the step and tolerance.



#2 0.25 step



Strategy

Maybe try the other direction.



#6 0.25 step 0.0025 scallop



Strategy


Top Down (Contour or Z-Level Finish)

#8 0.15 step down




Strategy

Constant Scallop Strategy




#7 0.16 step “snail tracks”




Strategy

Constant Scallop Strategy




#7 0.16 step “snail tracks”



Strategy

Pencil Trace – before you finish to reduce vibrations in concave corners



Tools


Tools

- The more rigid the tool the less deflection
- Shorter tools deflect and vibrate less
- Strong tool holders allow for stronger tools (shrink fit)
- The bigger the radius, the larger the step for the same scallop (means you can step less, finish faster)
- The more rigid the tool, the faster you can run and avoid effects of deflections and vibrations.

Tools



#11 3.175 Ball




#9 9.525 Ball




#4 6.35 0.25 Ball

Tools



Orange Peel
You can get interesting
harmonics if you use a 5
flute

Could probably run faster



Tools


Many machinists recommend the inserted contouring cutters



Tools

Many machinists recommend the inserted contouring cutters


#10 8mm ball



Tools

Tool plus strategy

#12 0.25 step 0.0025 scallop



A Story

How my friend Dave the Machinist got cut 5 strokes off his golf game. Dave is a one man job shop, and for every year, he makes tooling for creating small emblems for cars.



A Story

Dave would load and cut 10 molds at a time, and play a round of golf. He's return. Squirt the pieces with polishing compound and a 1/8" polisher, let it go, and play another round of golf.



A Story

And that's how Dave dropped 5 strokes from his golf game.

#15 polished



Questions?

Special Thanks to:



Power. Precision. Performance.



More Questions? Visit the AU Answer Bar & Manufacturing Area of the Exhibition Hall

- We have mills there.
- We have our expert Application Engineers
- Titan Gilroy is there and would love to talk shop



How did I do?

- Your class feedback is critical. Fill out a **class survey** now.
- Use the AU mobile app or fill out a class survey online.
- Give feedback after each session.
- AU speakers will get feedback in real-time.
- **Your feedback results in better classes and a better AU experience.**

