ReCap to the Max! How to Edit, Document, and Coordinate

Mark LaBell Jr.

Head of Innovation

About the speaker

Mark LaBell Jr

Head of Innovation, SSOE Group

Implemented first laser scan @ SSOE in 2008

Worked on 500+ scan projects

Worked closely with ReCap team on features

Started Hackathons and Innovation program

Construction Operations Building Information Exchange (COBie)

Internet of Things (IoT)

Common Data Environment (CDE)

MacLeamy Curve (IPD)

Federated BIM

Artificial Intelligence/Machine Learning (AIML)

Blockchain

Digital Twin

#DigitalOctuplet

Agenda

1. Interface overview
2. How to QA scans
3. Point Cloud cleanup
4. Demolition Man - this ain't Wesley Snipes' Point Clouds
5. Annotation and Assets
6. Navisworks Option-eering
7. Q&A

PSA on Coordinates

- State plane is still a disaster

- Program limitations

    - P3D 5000',5000'

    - Revit 20 miles

- Set a Building or Site monument. (IE 1000',1000',100')

- Do no move point clouds to fit design models

Example 0

- How do you QA a project in ReCap
  - Use pick limit box
  - Assign spray to region
  - Set color to scan position
  - Launch Project Navigator (jot down notes of colors)
  - Go back to registration

Example 1

- How to clean project
    - Create spray region
    - Assign spray to region
    - Export as spray file
    - Delete points and then do for rest of elements

Example 1 cont.

- Delete all points in the file
- Saveas to remove all points from RCS
  - Show folder on local computer
- Import P-Files from reference folder
- Review project navigator
- Create folders for scan positions vs point clouds
- Save

Example 2

- In Realview mode create a markup for demolition
- Repeat up to 4x
- Save file and review on recap360 website
- Connect iPad to show interchange for contractors
    - Switch to point cloud view
    - Use pick limit box, show rotation
    - Create demo region and assign points
- Show Bluebeam workflow if cloud not allowed per client

Example 3

- Dimension features
  - Pipe snap
  - Dim to surface, ortho
  - Show modification of dims
  - Add tag info to dims, pictures
- Import CSV File of comments
- Show search function
- Delete Demo region, attach Demo RCS file
- Attach NWD file

Example 4

- Open Navisworks Simulate
  - Factory Design plugin for viewing mirror bubbles
  - Voxel move

AUTODESK

Make anything.™