

Class Overview

IM119738 Fusion 360 Quick Tip Jam Session

Presenters:

Jamie Scherer Autodesk



Patrick Rainsberry Autodesk



Bryce Heventhal Autodesk



Learning Objectives

- Gain new ways to design, engineer, visualize, and manufacturer your products using Fusion 360
- Learn how to use new workflows to improve your speed and efficiency at each stage of the product development process
- Understand different selections, helper keys, commands, and workflows to help create products faster
- Learn how to complete tasks currently not possible, or in fewer clicks, using Fusion 360

Description

Are you a Fusion 360 master? Come to this session to step up your Fusion 360 skills. No matter what level of expertise you have with Fusion 360 3D CAD/CAM software, you'll leave this session with a few tricks up your sleeve. We'll cover some golden nuggets from every workspace in Fusion 360. Some tricks will help you model faster, a few will improve your computer's performance, and others are just plain cool. Come to this session to add some best practices to your Fusion 360 arsenal. Make sure to check out our weekly quick tips to prepare you for this session:

https://www.youtube.com/playlist?list=PLmA xUT-8UIIh4hHJDCEDLPi3wQiMrPRY



5 Favorite Quick Tips

1		
2.		
3.		
4.		
5.		
5 Nev	w Tips to Start Using To	<u>omorrow</u>
1		
2.		
3.		
4.		
5.		
Our F	avorite Tips (Check the bo	ox when you see it)
1.	S-Key	
2.	Midpoint Relationship	
3.	Between two Faces Joint	
4.	T-Splines Alt+Drag	
5.	Move Face/Extrude in Sheet	Metal
Our F	avorite Hot-Keys	
1.	Double Middle Mouse Click	=
2.	Cntl(光)+Shift+S	=
	Cntl(光)+ `	=
	Cntl(光) + ALT + DRAG	=
5.	SHIFT + N	=
0.		

Our Favorite Apps

Fusion 360 App store https://apps.autodesk.com/FUSION/en/Home/Index/

- 1. Sheetr
- 2. Boltr
- 3. Slicer for Fusion 360 (FKA 123D Make)
- 4. Bommer
- 5. Visual Styles



Helpful Links

Quick Tip Youtube Playlist

https://www.youtube.com/watch?v=N3bzKTeCJRk&list=PLmA_xUT-8UIIh4hHJDCEDLPi3wQiMrPRY

Getting Started w/ Fusion 360

https://www.autodesk.com/products/fusion-360/get-started

Keyboard Shortcuts

http://help.autodesk.com/view/fusion360/ENU/?guid=GUID-F0491540-0324-470A-B651-2238D0EFAC30

Support

http://help.autodesk.com/view/fusion360/ENU/?page=support

Ideastation

https://forums.autodesk.com/t5/fusion-360-ideastation-request-a/idb-p/125

Road Map

https://www.autodesk.com/products/fusion-360/blog/category/roadmap/

Forums

https://forums.autodesk.com/t5/fusion-360/ct-p/1234

Great Resources to keep learning:

- 1. Fusion 360 Youtube:
 - https://www.youtube.com/channel/UCiMwMz3RMbW5mbx0iDcRQ2g
- 2. Webinars: https://autodesk.wistia.com/projects/3gp20dlh9j
- NYCCNC: https://www.youtube.com/channel/UCe0lyK4ntgdPTTjsxjvyHPg
- 4. Lars-CADCAMSTUFF: https://www.youtube.com/user/cadcamstuff
- 5. Tyler Beck-TECH & ESPRESSO:
 - https://www.youtube.com/channel/UC VEo4EW9xoPPc4ZVmy4X7A/featured
- 6. Titans of CNC: http://academy.titansofcnc.com/category/learn-to-design-in-cad
- 7. Design Academy: https://academy.autodesk.com/getting-started-fusion-360



Keyboard Shortcuts:

				Canvas Selection	Windows Key Combinations	Mac Key Combinations
				Pan	Hold Middle Mouse Button	Hold Middle Mouse Button
				Zoom	Roll Middle Mouse Button	Roll Middle Mouse Button
				Orbit	Hold Shift + Hold Middle Mouse Button	Hold Shift + Hold Middle Mouse Button
Command		Key Combinations				
Extrude		F Combinations		Orbit around point	Hold Shift + Click then Hold Middle Mouse Button	Hold Shift + Click then Hold Middle Mouse Button
Hole		н		Undo	Ctrl + Z	Command + Z
Press Pull		Q		Redo	Ctrl + Y	Command + Y
Model Fillet		Ę.		Сору	Ctrl + C	Command + C
Move		M		Paste	Ctrl + V	Command + V
Toggle Visibility		M V		Cut	Ctrl + X	Command + X
Toggle Component Color Cycling		Shift + N				
Model Toolbox				Sculpt Workspace Selection	Windows Key Combinations	Mac Key Combinations
Appearance		A		Grow selection	Shift + Up Arrow	Shift + Up Arrow
				Shrink selection	Shift + Down Arrow	Shift + Down Arrow
Compute All		Crtl + B (Windows) or Command + B (Mac)		Loop selection	Alt + P	Control + P
Joint		J			Alt + O	Control + O
As-built Joint		Shift + J		Loop grow selection Ring selection	Alt + L	Control + U
Line		L			Alt + L	Control + K
2-point Rectangle		R		Ring grow selection		
Center Diameter Circle		C		Ring shrink selection	Alt+J	Control + J
Trim		Т		Previous U	Alt + Left Arrow	Control + Command + Left Arrow
Offset		0		Next U	Alt + Right Arrow	Control + Command + Right Arrow
Measure		I		Previous V	Alt + Down Arrow	Control + Command + Down Arrow
Project		P		Next V	Alt + Up Arrow	Control + Command + Up Arrow
Normal / Construction		X D		Range selection	Alt + M	Command + M
Sketch Dimension	Sketch Dimension			Invert selection	Alt + N	Command + N
Scripts and Add-ins		Shift + S		Toggle box mode	Alt + 1	Control + 1
Window Selection		1		Toggle control frame mode	Alt + 2	Control + 2
Freeform Selection		2		Toggle smooth mode	Alt + 3	Control + 3
Paint Selection		3		Select edge ring	Double-click an edge	Double-click an edge
Delete		Del		Select face ring	Select two faces then double-click a third face	Select two faces then double-click a third face
System Keyboard Shortcuts	Windows Key Combina	tions	Mac Key Combinations			
Create Version	Ctrl + S		Command + S	Edit Form Command	Windows Key Combinations	Mac Key Combinations
Recovery Save	Ctrl + Shift + S		Command + Shift + S	Add geometry	Alt + Drag	Alt + Drag
				Add geometry and keep creases	Alt + Ctrl + Drag	Alt + Command + Drag
Shortcuts for switching workspaces						
				Render Workspace Command	Windows Key Combinations	Mac Key Combinations
You can now switch workspaces with CTRL + Leftbracket and CTRL + Rightbracket key combos. Thi workspace in the order it is listed in the workspace switcher.			s will take you through the next and previous	Appearance	A	A
Animate Workspace Command	Windows Key Combinat	tions	Mac Key Combinations			
Transform Components	M					
			M			
Auto Explode All Levels	U		M U	CAM Workspace Command	Windows Key Combinations	Mac Key Combinations
	U E		U	CAM Workspace Command Generate Toolpath	Windows Key Combinations Ctrl + G	Mac Key Combinations Command + G
Auto Explode All Levels Manual Explode View	U E U		U E U			
Auto Explode All Levels Manual Explode	U E		U E	Generate Toolpath	Ctrl + G	Command + G
Auto Explode All Levels Manual Explode View Publish Video	U E U P		U E U P	Generate Toolpath Duplicate	Ctrl + G Ctrl + D	Command + G Command + D
Auto Explode All Levels Manual Explode View Publish Video Simulate Workspace Command	U E U P Windows Key Combination	tlons	U E U P Mac Key Combinations	Generate Toolpath Duplicate Show Log	Ctrl + G Ctrl + D Ctrl + L	Command + G Command + D Command + L
Auto Explode All Levels Manual Explode View Publish Video Simulate Workspace Command New Simulation Study	U E U P Windows Key Combinate N	tions	U E U P P Mac Key Combinations N	Generate Toolpath Duplicate Show Log Scripts and Add-Ins	Ctrl + G Ctrl + D Ctrl + L Shift + S	Command + G Command + D Command + L Shift + S
Auto Explode All Levels Manual Explode View Publish Video Simulate Workspace Command New Simulation Study Structural Constraint	U E U P Windows Key Combinat N C	ilons	U E U P P Mac Key Combinations N C	Generate Toolpath Duplicate Show Log Scripts and Add-Ins Drawing Workspace Command	Ctrl + G Ctrl + D Ctrl + L Shift + S Windows Key Combinations	Command + G Command + D Command + L Shift + S Mac Key Combinations
Auto Explode All Levels Manual Explode View Publish Video Simulate Workspace Command New simulation Study Structural Constraint Structural Loads	U E U P Windows Key Combinat N C L	tions	U E U P P Mac Key Combinations N C L	Generate Toolpath Duplicate Show Log Scripts and Add-Ins Drawling Workspace Command Projected View	Ctrl + G Ctrl + D Ctrl + L Shift + S Windows Key Combinations	Command + G Command + D Command + L Shift + S Mac Key Combinations P
Auto Explode All Levels Manual Explode View Publish Video Simulate Workspace Command New Simulation Study Structural Constaint Structural Loads Force	U E U P Windows Key Combinat N C L	ions	U E U P P Mac Key Combinations N C L F	Generate Toolpath Duplicate Show Log Scripts and Add-ins Drawling Workspace Command Projected View Move	Ctrl + G Ctrl + D Ctrl + L Shift + S Windows Key Combinations P M	Command + G Command + D Command + L Shift + S Mac Key Combinations P M
Auto Explode All Levels Manual Explode View Publish Video Simulate Workspace Command New Simulation Study Structural Constraint Structural Loads Force Model View	U E U P Windows Key Combinat N C L F Ctrl + L	ions	U E U P P Mac Key Combinations N C L F Command + L	Generate Toolpath Duplicate Show Log Scripts and Add-ins Drawing Workspace Command Projected View Move Delete	Ctrl + G Ctrl + D Ctrl + L Shift + S Windows Key Combinations P M Delete	Command + G Command + D Command + L Shift + S Mac Key Combinations P M Delete
Auto Explode All Levels Manual Explode View Publish Video Simulate Workspace Command New Simulation Study Structural Constraint Structural Loads Force Model View DOF View	U	ions	U E U P Mac Key Combinations N C L F Command + L Command + D	Generate Toolpath Duplicate Show Log Scripts and Add-ins Drawling Workspace Command Projected View Move Delete Center Mark	Ctrl + G Ctrl + D Ctrl + L Shift + S Windows Key Combinations P M Delete C	Command + G Command + D Command + L Shift + S Mac Key Combinations P M Delete C
Auto Explode All Levels Manual Explode View Publish Video Simulate Workspace Command New Simulation Study Structural Constraint Structural Constraint Structural Loads Force Model View DOF View Groups View	U	ions	U E U P P Mac Key Combinations N C L F Command + L Command + D Command + G	Generate Toolpath Duplicate Show Log Scripts and Add-Ins Drawling Workspace Command Projected View Move Delete Center Mark Dimension	Ctri + G Ctri + D Ctri + L Shift + S Windows Key Combinations P M Delete C D	Command + G Command + D Command + L Shift + S Mac Key Combinations P M Delete C D
Auto Explode All Levels Manual Explode View Publish Video Simulate Workspace Command New Simulation Study Structural Constraint Structural Loads Force Model View DOF View	U	idons	U E U P Mac Key Combinations N C L F Command + L Command + D	Generate Toolpath Duplicate Show Log Scripts and Add-ins Drawling Workspace Command Projected View Move Delete Center Mark	Ctrl + G Ctrl + D Ctrl + L Shift + S Windows Key Combinations P M Delete C	Command + G Command + D Command + L Shift + S Mac Key Combinations P M Delete C